



Número: 59 Fecha/Hora de Emisión: 2018-01-10T 08:17:14.818Z

Zona: ESPAÑA COSTA E ISLAS BALEARES

Tipo: OPERACIONES

Subtipo: MINI SUBMARINOS

Clasificación: Costero

Asunto: ESPAÑA COSTA E ISLAS BALEARES - OPERACIONES - MINI SUBMARINOS - NR-49/2018 - 2018/01/10 08:11:21

Texto Español: NR/00059/2018  
ESPAÑA COSTA E ISLAS BALEARES  
1.- CANALES DE IBIZA Y DENIA: OPERACIONES DE INSPECCION DE GASEODUCTO SUBMARINO CON VEHICULO SUBMARINO SUMERGIDO POR BUQUE DE BAHAMAS SKANDI CARLA/C6RX4.  
POSICION HASTA 101400UTCENE18, ATRACADO EN PALMA.  
POSICIÓN ESTIMADA EN 24H: 39-25.2N 002-30.6E  
POSICIÓN ESTIMADA EN 48H: 39-22.7N 002-17.4E  
SE SOLICITA A TODOS LOS BUQUES AL MENOS 1 MILLA DE RESGUARDO.  
ATENCION A LOS BUQUES PESQUEROS. SUS APAREJOS PUEDEN RESULTAR DAÑADOS Y SU SEGURIDAD COMPROMETIDA.  
2.- CANCELA NR49/18

English Text: NR/00059/2018  
SPAIN E COAST BALEARES ISLANDS  
1.- IBIZA AND DENIA CHANNELS: GAS PIPE LINE SURVEY USING ROV BY BAHAMIAN VESSEL SKANDI CARLA/C6RX4.  
POSITION TILL 101400UTCENE18, BERTHED IN PALMA.  
POSITION ESTIMATED IN 24H: 39-25.2N 002-30.6E  
POSITION ESTIMATED IN 48H: 39-22.7N 002-17.4E  
ALL VESSELS ARE REQUESTED TO KEEP 1 MILE BERTH. FISHING VESSELS COULD RESULT DAMAGE USING FISHING GEAR CLOSE TO THE OPERATIONS.  
2.- CANCEL NR49/18